

### Playsafety RoSPA Inspection June 2020

	Findings	Action	Name
<b>Berkeley Street Gate</b>	Large gap underneath gate to be filled	<b>Yes</b>	RW
	Encroaching vegetation on path/steps to be removed	<b>Yes</b>	CT
	Replace steps with ramp	<b>X</b>	-
	Hand rail and post decayed, to be replaced	<b>Yes</b>	Quotes to be obtained
<b>Bushes &amp; Trees</b>	All mature trees to be inspected regularly	<b>Yes</b>	Steve Bailey
	Trees and bushes to be maintained	<b>Yes</b>	Tom Cooper
<b>Chestnut Paling</b>	1 slat broken, to be replaced	<b>Yes</b>	GK & RW to inspect
<b>Bench</b>	Slats too far apart	<b>X</b>	-
	Encroaching vegetation to be removed	<b>Yes</b>	CT
<b>Litter bin</b>	Too close to bench	<b>X</b>	-
<b>Signage</b>	Dog Ban required	<b>X</b>	Already notices on gate
	Ownership	<b>X</b>	-"
	No kite flying	<b>Yes</b>	Clerk to source
<b>Wooden Barriers</b>	Loose supports, need re-setting	<b>X</b>	Dry ground
	Strimmer damage – prevent rot & further damage	<b>Yes</b>	Tom Cooper to be informed
<b>Picnic table</b>	Loose bolts to be tightened	<b>Yes</b>	RW

<b>Goal Posts</b>	Net clips to be replaced	<b>Yes</b>	RW to remove
	Rubber mats to be lifted and re-set	<b>Yes</b>	RW
<b>Basketball hoop</b>	Bolts missing, to be replaced	<b>Yes</b>	Clerk to source replacements
	Algae to be cleaned away	<b>Yes</b>	CT/PP
<b>Snail rocker</b>	Requires cleaning	<b>Yes</b>	CT/PP
<b>See-saw rocker</b>	Tighten hand holds	<b>Yes</b>	Clerk to source
	Loose item on hand hold	<b>Yes</b>	Clerk to source
<b>Pirate ship</b>	Cleaning bird foul away & disinfect	<b>Yes</b>	CT/PP
	Tighten net eye bolts	<b>Yes</b>	RW
	Grass growing under net ladder to be removed	<b>Yes</b>	RW
	Neck/head entrapment risk	<b>X</b>	-
<b>Basket swing</b>	Secondary support	<b>X</b>	
<b>Toddler swing</b>	Replace seat	<b>Yes</b>	Clerk to source
	shackles seized, to be loosened	<b>Yes</b>	GK & RW